2025 Division 12 STEP Operation and Maintenance Plan

January 28, 2025

Pump house

- Replace 2 iron pipe sections (2025)
- Monitor/replace exhaust fan--LOW
- Data logger- troubleshoot software--LOW

Terminal Vault Area

- Monitor vault flooding during major storm events (Winter-2025)
- Install floor drain standpipe or grate/screen after all drain work--LOW
- Clean aerator/grease lock—ANNUAL (2025)
- Data logger—functioning—requires good weather—LOW

Air Vac Release Assembly

Isolate/bypass Air Vacuum Release Valve (2025)

Overall System

• Exercise valves and inspect STEP-owned 24" lids—BI-ANNUAL (2025)

Documentation

Update Website Equipment Documentation—Ongoing

Community Focused I&I Maintenance—explore options (Decision April 2025)

• Lid Inspection program—all homes —Incentives? Contract or volunteer, both? (potential 2025)